

No. Bldg. Permit	Bldg. Per. Issued	Work Stopped	Cons. not Approved	Steel not Approved	Spl. Insp. Not App'd	Cert. Oc. Required	Floor Cds. Required	No F. E. Permit	Not Accepted	Exits not Approved	No W. A. Htg. Per.	No Rough Inspection	No Final Inspection	No St. Htg. Per.	No Rough Inspection	No Final Inspection	No Boiler Permit	No Final Accept.	No Elev. Permit	No Final Inspection	Sta. Cur. not Appr.	No Tank Permit	No Final Accept.	Spr. Sys. Required	Standpipes Required	Gas S. O. Required	No Plb. Permit	No Rough Inspection	No Final Inspection	Booth not Appr.	Street Per. Required
------------------	-------------------	--------------	--------------------	--------------------	----------------------	--------------------	---------------------	-----------------	--------------	--------------------	--------------------	---------------------	---------------------	------------------	---------------------	---------------------	------------------	------------------	-----------------	---------------------	---------------------	----------------	------------------	--------------------	---------------------	--------------------	----------------	---------------------	---------------------	-----------------	----------------------

Street Do. 51 No. 105 Class III Type Brick durg
 Lot 20 Block 78 Dunder Place Addition
 Owner M. M. Murray Architect C. W. Rosenberg
 Bldg. Contr. Stow & Anderson Cost \$ 8000 HEATING, KIND OF 189

Proscenium Wall—Constr.	Stage Curtain	Stage Constr.
Exits, Regular Number of	Exits, Emergency Number of	Booth, Constr. and Size of
Building Permit No. <u>954</u> Date <u>5-15-22</u>	W. A. Heating Permit No. _____ Date _____	Plumbing Permit No. _____ Date _____
Reinf. Conc. Str. Steel _____ Appr. _____	Stack Insp'n. _____ No. of Outlets _____	Sink _____ Laundry Trays _____
Plans Passed by _____ Plans On File _____	Final Insp'n. _____	Closet _____ Urinal _____
Special Inspector _____	St. Heating Permit No. _____ Date _____	Basin _____ Bar Connect. _____
Inspections No. of _____	Rough Insp'n. _____ Rad'n. Feet _____	Bath _____ Ice Box _____
Framing Inspection _____	Final Insp'n. _____	Floor Drain _____ Drinking Fountain _____
Certificate of Occupancy _____	Boiler Permit No. _____ Date _____	Total No. Fixtures _____
Floor Load Cards Issued _____	Boiler Type _____ Size _____	Roughing Inspection <u>2620</u>
Auto. Gas Valve Number Req'd. _____ Notice to Install _____	Boiler Make _____ No. _____	Final Inspection _____
Certificate of Inspection No. _____ Date _____	Boiler Furnace _____	Elevator Permit No. _____ Date _____
Fire Escape Permit No. _____ Date _____	Installation Accepted _____	Passenger _____
Type _____ Number Installed _____	Roof Tank Permit No. _____ Date _____	Freight _____
Exits Approved _____	Type _____ Size _____ No. _____	Sidewalk _____
Final Insp'n. _____	Final Inspection _____	Dumb W. _____
Standpipes Approved _____ Final Insp'n. _____	Sprinkler System Approved _____ Final Insp'n. _____	Final Insp'n. _____ Insp'n. Number _____

51 2. 62

Contractor	
Roof Tank	
Contractor	
Sprinkler	
Contractor	
Fire Escape	

2621