

No. Bldg. Permit 522 Do. 51<sup>st</sup> ST. Office 522-24 Do. 51<sup>st</sup> ST.  
 Bldg. Per. Issued 522-24  
 Work Stopped  
 Conc. not Approved  
 Steel not Approved  
 Spl. Insp. Not Atd.  
 Cert. On Required  
 Floor C's Required  
 No F. E. Permit  
 Not Accepted  
 Exits not Approved  
 No W. A. Htg. Per.  
 No Rough Inspection  
 No Final Inspection  
 No St. Htg. Per.  
 No Rough Inspection  
 No Final Inspection  
 No Boiler Permit  
 No Final Accept.  
 No Elev. Permit  
 No Final Inspection  
 Sta. Cur. not Appr.  
 No Tank Permit  
 No Final Accept.  
 Spr. Sys. Required  
 Stand'p's Required  
 Gas S. O. Required  
 No Pib. Permit  
 No Rough Inspection  
 No Final Inspection  
 Booth not Appr.  
 Street Per. Required

Street Do. 51 No. 522 Class III Type dwg.  
 Lot 30 Block 3 Lockwood Terrace Addition  
 Owner L. A. Hickman Architect J. L. Conley  
 Bldg. Contr. Ben E. Ecklund Cost \$ 6200 HEATING, KIND OF 18"

Proscenium Wall—Constr.	Stage Curtain	Stage Constr.
Exits, Regular Number of	Exits, Emergency Number of	Booth, Constr. and Size of
Building Permit No. <u>475</u> Date <u>3-26-20</u>	W. A. Heating Permit No. _____ Date _____	Plumbing Permit No. _____ Date _____
Reinf. Conc. Str. Steel _____ Appr. _____	Stack Insp'n. _____ No. of Outlets _____	Sink _____ Laundry Trays _____
Plans Passed by _____ Plans On File _____	Final Insp'n. _____	Closet _____ Urinal _____
Special Inspector _____	St. Heating Permit No. _____ Date _____	Basin _____ Bar Connect. _____
Inspections No. of _____	Rough Insp'n. _____ Rad'n. Feet _____	Bath _____ Ice Box _____
Framing Inspection _____	Final Insp'n. _____	Floor Drain _____ Drinking Fountain _____
Certificate of Occupancy _____	Boiler Permit No. _____ Date _____	Total No. Fixtures _____
Floor Load Cards Issued _____	Boiler Type _____ Size _____	Roughing Inspection <u>275A</u>
Auto. Gas Valve Number Req'd. _____ notice to install _____	Boiler Make _____ No. _____	Final Inspection _____
Certificate of Inspection No. _____ Date _____	Boiler Furnace _____	Elevator Permit No. _____ Date _____
Fire Escape Permit No. _____ Date _____	Installation Accepted _____	Passenger _____
Type _____ Number Installed _____	Roof Tank Permit No. _____ Date _____	Freight _____
Exits Approved _____	Type _____ Size _____ No. _____	Sidewalk _____
Final Insp'n. _____	Final Inspection _____	Dumb W. _____
Standpipes Approved _____ Final Insp'n. _____	Sprinkler System Approved _____ Final Insp'n. _____	Final Insp'n. _____ Insp'n. Number _____

Contractor  
Heating

Contractor  
Plumbing

Contractor  
Elevator

Contractor  
Roof Tank

Contractor  
Sprinkler

Contractor  
Fire Escape

NOTIONS ON PLANS

DEFECTS IN CONSTRUCTION

ANNUAL INSPECTION NOTATIONS

2757