

APPLICATION FOR BUILDING PERMIT

Housing & Community Development Department — Permits & Inspections Division

80912

Street Capitol Ave No. 5709 Permit No. 894 Date Issued 2-31-81

Structure Repair Type _____ Size _____ Cost \$ 1,400⁰⁰

Stories _____ Rooms _____ Units _____ Type Garage _____ Fee \$ 8.00

Lot 5 Block 94 Addition Dundee

Size of Lot _____ Zone R5 p.122 Cor. Lot NO Fire Limits _____

Owner Roland J. Gardner Address 5709 Capitol Ave Ph. No. 553-7546

Contractor Owner Address _____ Ph. No. _____


Utilities: Sewer _____ Water _____ Power _____ Gas _____ Architect _____

Final Inspections: Bldg. _____ Elec. _____ Mech. _____ Plbg. _____ C. O. No. _____

This Structure to be Used as: General Repair Dwelling + Porch Appeal Case No. _____

Sur: Cert. _____ Plans on File Yes Reel No. _____ Checked by FB Date 3/30/81


Curb Cut _____ ft. Curb Cut Permit No. _____

 BPI-61

Roland J. Gardner 01046
Applicant Date 3-23-81

Plot Plan (Give All Dimensions)

01047



Indicate North

Front Setback: **Rear Yard:**

Side Yards--Left: _____ **Right:** _____

Footing Inspection

Rough-in Inspection _____
Inspector _____
Date _____

Inspector

Date _____