Cert. Req.	Floor Req.	No. Pa.	No F. Inspection	No St. Htg. Per.	No Rough Inspection	No Final Inspection	No Boiler Permit	No Final Accept.	No Elev. Permit	No Final Inspection	Sta. Cur. not Appr.	No Tank Permit	No Final Accept.	Spr. Sys. Required	Standpipe Required	Gas S. O. Required	No Pile Permit	No Rough Inspection	No Final Inspection	Booth not Appr.	Street Per. Required

e Ave No 5010 5010 Capitol Ave Class III Type Brick Tiner

Lot 20 Block 96 Dundee Addition

Harte Architect

owner Cost $ 5000.00 Heating, Kind of W. A.

		Stage Curtain		Stage Constr.	
		Exits, Emergency Number of		Booth, Constr. and Size of	
17	Date Aug. 9. 1918	W. A. Heating Permit No.	Date	Plumbing Permit No. 580	Date 9-20-18
		Stack Insp'n	No. of Outlets	/ Sink	Laundry Trays
M. B.	Plans On File Yes	Final Insp'n		/ Closet	Urinal
		St. Heating Permit No.	Date	/ Basin	Bar Connect.
8/18-8/19/18-8/29/18 9/14/18		Rough Insp'n	Rad'n Fest	/ Bath	Ice Box
	10-25-18-HEW	Final Insp'n		/ Floor Drain	Drinking Fountain
		Boiler Permit No.	Date	Total No. Fixtures 5	
		Boiler, Type	Size	Rough'ng Inspection 9-20-18 Lynch	
...alve Req'd	Notice to Install	Boiler, Make	No.	Final Inspection	
C... Inspec... No.	Date	Boiler Furnace		Elevator Permit No.	Date
F're Escape Permit No.	Date	Installation Accepted		Passenger	
Type	Number Installed	Roof Tank Permit No.	Date	Freight	
Exits Approved		Type	Size No.	Sidewalk	00930
Final Insp'n		Final Inspection		Dumb W.	
Standpipes Approved F.C. 11	Final Insp'n	Sprinkler System Approved	Final Insp'n	Insp'n Number	Final Insp'n

Contractor Heating	Comet Pipe & S.	Contractor Roof Tank	
Contractor Plumbing	C H. Kessler	Contractor Sprinkler	
Contractor Elevator		Contractor Fire Escape	

NOTATIONS ON PLANS	DEFECTS IN CONSTRUCTION	ANNUAL INSP

00981