

APPLICATION FOR BUILDING PERMIT

Housing & Community Development Department — Permits & Inspections Division


73608

Street Capital Av No. 5109 Permit No. 4906 Date Issued 10-22-80
Structure Repair Type _____ Size _____ Cost \$ 500
Stories _____ Rooms _____ Units _____ Type Garage _____ Fee \$ 5.00
Lot 5 Block 94 Addition Dundee Place
Size of Lot _____ Zone R-5 P-122 Cor. Lot _____ Fire Limits _____
Owner Roland J. Gardner Address 5109 Capital Av Ph. No. 553-7546
Contractor Owner Address _____ Ph. No. _____
Utilities: Sewer _____ Water _____ Power _____ Gas _____ Architect _____
Final Inspections: Bldg. _____ Elec. _____ Mech. _____ Plbg. _____ C. O. No. _____
This Structure to be Used as: Repair Porch / Dwg Appeal Case No. _____
Sur: Cert. _____ Plans on File _____ Reel No. _____ Checked by RS Date 10/22/80
Curb Cut _____ ft. Curb Cut Permit No. _____

BPI-61

Roland J. Gardner
Applicant Date 10/22/80

PLOT PLAN (Give All Dimensions)



Indicate North

01351

Front Setback: _____ Rear Yard: _____

Side Yards—Left: _____ Right: _____

Footing Inspection _____
Rough-in Inspection _____

Inspector _____

Date _____