

Bldg.										Plumbing										Mechanical										Electrical										Other									
Permit	Front	Side	Rear	Interior	Defective Work	Work Stopped	Not Inspected	Approved	Steel Not Approved	Cut On Retainer	Floor Ribs Not	Frame Joints Called for	No. High-Permit	High-Permit Issued	Defective Vign.	Work Stopped	Stack Insp'n	Final Insp'n	No. Bldg. Permit	Bldg. Permit Issued	No. Pile Permit	Pile Permit Issued	Pipe (Inch) Called for	No. Gas Permit	Tank Per. Issued	Not Accepted	Standpipes Required	Not Accepted	Spec Sys. Required	Not Accepted	No. Elev. Permit	Elev. Permit Issued	Ins. Permit	Ins. Permit Issued	Not Inspected	Not Inspected													
Street <u>Karnam</u>										No. <u>4823</u> <u>4821</u>										Class <u>III</u>										Type <u>Frame</u>																			
Lot <u>6</u>										Block <u>3</u>										<u>Sundat</u>										Addition																			
Owner <u>N.E. Pender</u>										Architect <u>Fred Peterson</u>																																							
Bldg. Contr. <u>Carl O. Johnson</u>										Heating Kind of <u>P H</u>																																							
Processium Wall—Constr.										Stage Curtain <u>Off. 4821-23</u>										Stage Constr.																													
Exits, Regular Number of										Exits, Emergency Number of <u>Bldg 4821</u>										Booth, Constr. and Size of																													
Building Permit No. <u>392</u> Date <u>4/28/16</u>										Heating Permit No. <u>Shawn</u> Date										Plumbing Permit No. <u>538</u> Date <u>5/16/16</u>																													
Reinforced Conc. Str. Steel Appr.										Stack Insp'n										Roof Tank Permit No.										Date																			
Plans Passed by <u>J.P.G.</u>										Final Insp'n										Type																													
Plans On File <u>no</u>										Boiler Permit No.										Final Insp'n																													
Special Inspector										Boiler, Kind										Number Installed																													
Final Inspection										Boiler, Size										Standpipes Approved																													
Certificate of Occupancy										Boiler, Make										Sprinkler System Approved																													
Floor Loads Cards issued										Boiler Furnace										Final Insp'n																													
Auto. Gas Valve Req'd										Fire Escape Permit No.										Final Insp'n										1770																			
Notice to Install No. date										Type										Elevator Permit No.										Date																			
Certificate of Insp'n No. Date										Final Insp'n										Type										Number Installed																			
Number Installed										Number Installed										Final Insp'n																													

Contractor  
Heating

Contractor  
Plumbing

Contractor  
Elevators

*Schellman Bros*

Contractor  
Roof Tank

Contractor  
Sprinkler

Contractor  
Fire Escape

NOTATIONS ON PLANS

DEFECTS IN CONSTRUCTION

ANNUAL INSPECTIONS—NOTATIONS

#869-4/18/50 - Morris Epstein - Move garage  
4819 farnegs to rear of 4821 farnegs  
Pour concrete footings - 4' x 4' x 4'  
6' x 12' 9"

Plot. R

1771