

PL 5609 077-5609-11

No. Bldg. Permit Issued	Work Stopped	Cons. not Approved	Steel not Approved	Sp. Insp. Not Appld	Curt. Os. Required	Floor O'ds Required	No F. E. Permit	Not Accepted	Exits not Approved	No W. A. Htg. Per.	No Rough Inspection	No Final Inspection	No St. Htg. Per.	No Rough Inspection	No Final Inspection	No Boiler Permit	No Final Accept.	No Elev. Permit	No Final Inspection	Sp. Cur. not Appr.	No Tank Permit	No Final Accept.	Sur. Sys. Required	Standp'ns Required	Gas S. O. Required	No Pib. Permit	No Rough Inspection	No Final Inspection	Booth not Appr.	Stagn. Per. Permitted
-------------------------	--------------	--------------------	--------------------	---------------------	--------------------	---------------------	-----------------	--------------	--------------------	--------------------	---------------------	---------------------	------------------	---------------------	---------------------	------------------	------------------	-----------------	---------------------	--------------------	----------------	------------------	--------------------	--------------------	--------------------	----------------	---------------------	---------------------	-----------------	-----------------------

Street Jones No. 5609 Class III Type Tr. Wdg

Lot 3 Block H Addition Greenleaf

Owner E. W. Bedford Architect C. J. Mahler

Bldg. Contr. C. J. Mahler Cost \$ 7500 Heating Kind of Hot air

Proscenium Wall—Constr.	Stage Curtains	Stage Constr.
Exits, Regular Number of	Exits, Emergency Number of	Roofs, Constr. and Size of
Building Permit No. <u>1835</u> Date <u>8-4-23</u>	W. A. Heating Permit No. _____ Date _____	Plumbing Permit No. _____ Date _____
Relnf. Cons. Str. Steel <u>As Appr</u>	Stack Insp'n _____ No. of Outlets _____	Sink _____ Laundry Trays _____
Plans Passed by <u>ASG</u> Plans On File <u>no.</u>	Final Insp'n _____	Closet _____ Urinal _____
Special Inspector _____	St. Heating Permit No. _____ Date _____	Basin _____ Bar Connect. _____
Inspections No. of _____	Rough Insp'n _____ Rad'n Test _____	Bath _____ Ice Box _____
Framing Inspection _____	Final Insp'n _____	Floor Drain _____ Drinking Fountain _____
Certificates of Occupancy _____	Boiler Permit No. _____ Date _____	Total No. Fixtures _____
Floor Load Cards Issued _____	Boiler, Type _____ Size _____	Roughing Inspection _____
Auto. Gas Valve Number Req'd _____ Notice to Install _____	Boiler, Make _____ No. _____	Final Inspection _____
Certificate of Inspection No. _____ Date _____	Boiler Furnace _____	Elevator Permit No. _____ Date _____
Fire Escape Permit No. _____ Date _____	Installation Accepted _____	Passenger _____
Type _____ Number Installed _____	Roof Tank Permit No. _____ Date _____	Freight _____
Exits Approved _____	Type _____ Size _____ No. _____	Sidewalk _____
Final Insp'n _____	Final Inspection _____	Dumb W. _____
Standpipes Approved _____ Final Insp'n _____	Sprinkler System Approved _____ Final Insp'n _____	Ins'n Number _____ Final Insp'n _____

(0-3426)

Contractor
Heating

Contractor
Plumbing

Contractor
Elevator

Contractor
Roof Tank

Contractor
Sprinkler

Contractor
Fire Escape

e 362

Plot 80

NOTIONS ON PLANS

DEFECTS IN CONSTRUCTION

ANNUAL INSPECTION NOTATIONS

3427