

BUILDING PERMIT AND C. O. RECORD
OMAHA BUILDING DEPARTMENT

B-61-5-30-51

✓—Yes

Street Jones No. 5635 Permit No. 3818 Date 4/20/53
Structure Repair fire damage Type _____ Cost \$ 1500⁰⁰
Stories _____ F. Units _____ Cor. Lot by Fire Limits _____ Fee \$ 8⁵⁰
Lot _____ Block _____ Addition _____
Size of Lot _____ Zone _____ District _____
Owner Wm William Kelly Address 6631 Milvay
Contractor J E Morten & Son Architect _____
Utilities: Sewer _____ Water _____ Power _____ Gas _____
Final Inspections: Bldg _____ Elec _____ Mech _____ Plbg _____
Certificate of Occupancy No. _____ Date _____
Plans on File _____ Checked by J E Morten & Son Date 4-20-53
Sur. Cert. _____ By J E Morten **3972**

Plot Plan and Remarks on Reverse Side

3473

343