

|                                 |                   |                    |                    |                           |                      |                    |                     |                  |              |                    |                     |                     |                     |                  |                     |                     |                  |                  |                 |                     |                     |                |                  |                    |                     |                    |                |                     |                     |                 |                      |
|---------------------------------|-------------------|--------------------|--------------------|---------------------------|----------------------|--------------------|---------------------|------------------|--------------|--------------------|---------------------|---------------------|---------------------|------------------|---------------------|---------------------|------------------|------------------|-----------------|---------------------|---------------------|----------------|------------------|--------------------|---------------------|--------------------|----------------|---------------------|---------------------|-----------------|----------------------|
| No. Bldg. Permit                | Bldg. Per. Issued | Work stopped       | Comm. and approval | Steel not Approved        | Spl. Insp. Not Ap'd. | Cert. Op. Required | Floor C'ds Required | No. F. E. Permit | Not Accepted | Exits not Approved | No. W. A. Htg. Per. | No Rough Inspection | No Final Inspection | No St. Htg. Per. | No Rough Inspection | No Final Inspection | No Boiler Permit | No Final Accept. | No Elev. Permit | No Final Inspection | Sta. Cur. not Appr. | No Tank Permit | No Final Accept. | Sig. Sys. Required | Standpipes Required | Gas S. O. Required | No Flt. Permit | No Rough Inspection | No Final Inspection | Booth not Appr. | Street Per. Required |
| Street <u>Jones</u>             |                   | No. <u>5233</u>    |                    | Class <u>Brick Veneer</u> |                      | Type <u>Garage</u> |                     |                  |              |                    |                     |                     |                     |                  |                     |                     |                  |                  |                 |                     |                     |                |                  |                    |                     |                    |                |                     |                     |                 |                      |
| Lot <u>P</u>                    |                   | Block <u>7</u>     |                    | Addition <u>Lockwood</u>  |                      |                    |                     |                  |              |                    |                     |                     |                     |                  |                     |                     |                  |                  |                 |                     |                     |                |                  |                    |                     |                    |                |                     |                     |                 |                      |
| Owner <u>H. G. Hamann</u>       |                   | Architect          |                    |                           |                      |                    |                     |                  |              |                    |                     |                     |                     |                  |                     |                     |                  |                  |                 |                     |                     |                |                  |                    |                     |                    |                |                     |                     |                 |                      |
| Bldg. Contr. <u>A. Borchman</u> |                   | Cost \$ <u>500</u> |                    | Heating Kind of <u>—</u>  |                      |                    |                     |                  |              |                    |                     |                     |                     |                  |                     |                     |                  |                  |                 |                     |                     |                |                  |                    |                     |                    |                |                     |                     |                 |                      |

|  |  |                                      |
|--|--|--------------------------------------|
| Proscenium Wall—Constr.                              | Stage Curtains                               | Stage Constr.                        |
| Exits, Regular Number of                             | Exits, Emergency Number of                   | Booth, Constr. and Size of           |
| Building Permit No. <u>1349</u> Date <u>7/19-15</u>  | W. A. Heating Permit No. _____ Date _____    | Plumbing Permit No. _____ Date _____ |
| Reinf. Conn. Str. Steel } Appr.                      | Stack Insp'n No. of Outlets                  | Sink Laundry Trays                   |
| Plans Passed by _____ Plans On File                  | Final Insp'n                                 | Closet Urinal                        |
| Special Inspector                                    | St. Heating Permit No. _____ Date _____      | Basin Bar Connect.                   |
| Inspections No. of                                   | Rough Insp'n Rad'n Feet                      | Bath Ice Box                         |
| Framing Inspection                                   | Final Insp'n                                 | Floor Drain Drinking Fountains       |
| Certificate of Occupancy                             | Boiler Permit No. _____ Date _____           | Total No. Fixtures                   |
| Floor Load Cards Issued                              | Boiler, Type _____ Size _____                | Roughing inspection                  |
| Auto. Gas Valve Number Req'd _____ Notice to install | Boiler, Make _____ No. _____                 | Final inspection                     |
| Certificate of Inspection No. _____ Date _____       | Boiler Furnace                               | Elevator Permit No. _____ Date _____ |
| Fire Escape Permit No. _____ Date _____              | Installation Accepted                        | Passenger                            |
| Type _____ Number installed                          | Roof Tank Permit No. _____ Date _____        | Freight                              |
| Exits Approved                                       | Type _____ Size _____ No. _____              | Sidewalk <u>11/1/98</u>              |
| Final Insp'n   | Final inspection                             | Dumb W.                              |
| Standpipes Approved _____ Final Insp'n               | Sprinkler System Approved _____ Final Insp'n | Insp'n Number _____ Final Insp'n     |

Contractor  
Heating

Contractor  
Plumbing

Contractor  
Elevator

Contractor  
Roof Tank

Contractor  
Sprinkler

Contractor  
Fire Escape


C-360

P-80

NOTATIONS ON PLANS

DEFECTS IN CONSTRUCTION

ANNUAL INSPECTION NOTATIONS



3399